AFTER THE KINGTIDE

Fripp Island - Shoreline Committee

Darryl Zoeckler - November 9, 2021

THE SOUTH END

High Tide



South Tarpon facing north.



South Tarpon facing north.



South Tarpon facing north.



The remains of the forested land mass that once surrounded the old dormitory.

THE INTERIOR

High Tide



The marina



Beach Club Villas/ canal



Tennis Villas



Tarpon/Sawgrass boardwalk



Sawgrass neighborhood



Fiddlers Ridge neighborhood



Marsh Dunes Road/ Fiddlers

THE SALT MARSH


Between River Club and Porpoise Drive



Overall view of the salt marsh at high tide. The breaking waves in the center of the damaged area demonstrates the wave action that's causing the damage.



The damaged area next to the Mollura residence.



Without the salt marsh, this seawall will become the only protection for the homes along River Club and Cardinal Crest.



The volume of wrack pushed to the end of the salt marsh in front of the Deer Lake/Blue Heron Lake spillway.



The volume of wrack in context to its surroundings.

BRIDGE ABUTMENT

High Tide



Fripp bridge abutment.



Fripp bridge abutment.



Fripp bridge abutment.

AERIAL PHOTOGRAPHY

All Images were captured via drone at high tide on November 9, 2020.